



MODEL 8700

X-RAY PULSE COUNTER / EXPOSURE TIME METER INSTRUCTION MANUAL

TABLE OF CONTENTS

OVERVIEW	2
DESCRIPTION	2
GENERAL INSTRUCTIONS	3
BATTERY REPLACEMENT	5
WARRANTY	5
CALIBRATION	5
SERVICE INFORMATION	5
EXPOSURE TIME CONVERSION CHART	6
SPECIFICATIONS	7
APPENDIX	8

db:\8700c\manual_8700c



Electronic Control Concepts

PO Box 182, 1160 US Route 50
Milford, Ohio 45150-9705 USA
Phone: 800-VIP-XRAY

Fax: 845-247-9028

sales@eccxray.com | www.eccxray.com
A Division of US Nuclear Corp
www.usnuclearcorp.com

OVERVIEW

This instruction manual applies to Electronic Control Concepts Model 8700 for Serial Numbers 7001 and above. Significant design improvements have been made to this version of the Model 8700 including:

- 1) Ability to measure pulsed x-ray time in milliseconds as well as count pulses.
- 2) Improved sensitivity which means that we can measure exposure time of very low level x-rays.
- 3) Improved x-ray intensity range allows use with high energy x-rays.
- 4) Exposure time accuracy is now 1%.
- 5) Multi character display makes operation and understanding of results easier.

DESCRIPTION

The ECC Model 8700 X-ray Timer/Counter is used to measure the duration of radiation output produced by X-ray generators. The ECC Model 8700 is a solid-state, digital instrument designed specifically for service personnel in assessing the performance of radiation generator timing controls. The instrument is a noninvasive instrument, which samples the radiation beam of x-rays.

The Model 8700 can be used as follows:

- 1) To count the number of x-ray pulses produced by half-wave and full-wave rectified machines. It will count the output pulses typically 60 pulses per second for half-wave rectified machines or 120 pulses per second for full-wave. Dental x-ray machines are usually half-wave rectified.
- 2) To measure the exposure time of x-ray pulses produced by half-wave and full-wave x-rays. This is a new function, and is the only Exposure Time Meter available with this capability.
- 3) To measure the length of radiation output when the x-ray output is steady state such that "pulsing" does not exist. X-rays that generate steady outputs include 3-phase AC medical x-ray machines; capacitor discharge x-ray machines and DC operated x-rays.
- 4) To measure the "on time" or relay contact closure time by counting the number of pulses of AC line voltage (90 to 130 VAC) via the front panel input jacks and test leads.

The Model 8700 replaces not only mechanical impulse counters, but also other electronic counters. The small hand held size conveniently fits in a small toolbox, jacket pocket or handbag.

There is no "Reset" button. The Model 8700 automatically resets at the beginning of each exposure, holding the reading until the next exposure.

The most convenient way of using the 8700 is to place it directly under the x-ray head, step back, take the exposure and then read the exposure time in pulses or milliseconds.

It is important that the user be thoroughly familiar with the contents of this manual before performing any tests on radiation generating equipment. It is also imperative that the user be thoroughly qualified, and familiar with safety precautions and other practices relating to radiation generators.

GENERAL INSTRUCTIONS

Switch Settings

The front panel selector toggle switch on the Model 8700 has 3 positions, 'OFF', 'PULSES', and 'MILLISECONDS'. The switch is OFF in the center position.

PULSES

When the switch is moved to the 'PULSES' position, the instrument will be used for measuring (or counting) output pulses from half-wave or full-wave rectified machines as well as AC line voltage pulses. Normally (in USA), each full second of exposure will produce 60 pulses. An exposure of 2/10 second will read 12 for example. Refer to the chart on page 5 for further illustration.

MILLISECONDS

With the switch in the 'MILLISECONDS' position, the instrument will measure the length of time that a DC or 3-phase AC x-ray is on. The display reading will be in milliseconds i.e. an exposure of 1 second will read 1000, an exposure of 2/10 second will read 200. This switch position can also be used for measuring the exposure time of pulsed x-rays.

OFF

All power to the instrument is disconnected in the 'OFF' position. Set the switch to 'OFF' when not in use to conserve battery life. The center position is OFF.



Connections

When reading directly from an x-ray head, no connections are made to the instrument. Point the x-ray head at the "target" area of the Model 8700. Take an exposure and read the time on the display in pulses or milliseconds.

AC Input

Connect the test leads to the two input jacks on the front of the instrument. Since the instrument counts AC pulses, the AC line must be switched by the relay that is in the timer under test. A typical wiring configuration is shown in schematic form in Figure 1. A typical wiring configuration for testing an ECC Model 8200A Timer is shown in Figure 2. When using the AC mode, the switch must be in the PULSE position.

The circuit for AC inputs is completely isolated from the rest of the instrument. No damage to the instrument will occur if the probes are reversed. If the count is off by one pulse, try reversing the leads.



Preheat Concern

Some x-ray machines emit low level radiation during the pre-heat cycle. The sensitive detection circuit will respond to this spurious radiation, which should not be present. If your measured exposure time is significantly higher than what is expected, the instrument could be responding to preheat emission. To minimize the error from preheat radiation, increase the distance from the x-ray source to the 8700 or put an aluminum filter over the front of the instrument.

BATTERY REPLACEMENT

The Model 8700 is supplied with one 9 Volt Alkaline battery. Replace the battery when the "Lo Bat" indicator shows in the display. Any standard 9 Volt Alkaline battery can be used in the 8700. To meet the battery life specification, please use a Duracell MN1604 Battery. This is the familiar "gold top" battery. To prolong battery life, turn the instrument off when not in use.

To replace the battery, slide the battery compartment open on the bottom of the case. Remove the old battery, and install the new battery.

This instrument measures and displays the actual battery voltage every time the unit is switched on. The second line of the display momentarily shows B= X.XV. This gives the operator an indication of how much battery life is left. When the battery voltage drops below 5.8 Volts, a Low Battery warning will be displayed. Please change the battery as soon as possible.

We suggest removing the battery when shipping the instrument or if it will not be used for a long period of time.

WARRANTY

Electronic Control Concepts warrants the Model 8700 X-ray Timer/Counter from defects in materials and workmanship for a period of two years. There is no warranty on the battery. ECC will replace or repair any Model 8700 during the first two years after shipment that does not show obvious signs of abuse. Contact the factory as described below.

CALIBRATION

We recommend yearly calibration, test and verification. ECC will test and issue calibration certificates. To return a unit for calibration, contact ECC as shown below under Service Information. Please include a return address and either credit card information or contact information so that we can get credit card information.

SERVICE INFORMATION

If a unit should need service, please contact the factory by email or phone (see front cover of this manual) to obtain a Return Materials Repair authorization. Please ship with battery removed.

After obtaining an RMR number, ship the unit to:

- 6

Electronic Control Concepts
160 Partition Street
Saugerties, NY 12477

EXPOSURE TIME CONVERSION CHART

Impulses	Time in Seconds	Time in Seconds	Time in Seconds
1	0.02	0.02	0.01
2	0.03	0.04	0.02
3	0.05	0.06	0.03
4	0.07	0.08	0.03
5	0.08	0.1	0.04
6	0.1	0.12	0.05
7	0.12	0.14	0.06
8	0.13	0.16	0.07
9	0.15	0.18	0.08
10	0.17	0.2	0.08
15	0.25	0.3	0.13
20	0.33	0.4	0.17
25	0.42	0.5	0.21
30	0.5	0.6	0.25
35	0.58	0.7	0.29
40	0.67	0.8	0.33
45	0.75	0.9	0.38
50	0.83	1	0.42
60	1	1.2	0.5
70	1.17	1.4	0.58
80	1.33	1.6	0.67
90	1.5	1.8	0.75
100	1.67	2	0.83
120	2	2.4	1
150	2.5	3	1.25
180	3	3.6	1.5
200	3.33	4	1.67
240	4	4.8	2
	60 Hz Line	50 Hz Line	Full Wave
	USA, Canada	Europe	@ 60 Hz

The formulas for determining exposure time based on number of pulses is as follows:

Time (in seconds) = pulses / 60 for half wave x-ray in USA or Canada

Time (in seconds) = pulses / 120 for full wave x-ray in USA or Canada

Time (in seconds) = pulses / 50 for half wave x-ray in Europe and countries with 50 Hz line.

Model 8700 SPECIFICATIONS

Accuracy

- AC Input / X-ray Pulse - +/- 1 Count
- DC Input - 1% +/- 1 Count
 - Measures at 50% of peak value

Sensitivity

- AC Input - 90 VAC minimum
- X-ray input - 40kVp, 3mA at 5 cm from top surface of case, pointed to target on case.

Maximum Measurement Time

- Pulses
 - 65,536
 - 18 minutes
- Milliseconds
 - 65,536
 - 65.5 seconds

Display

- 0.21" (5.5mm) Character height,
- 2 lines by 12 Characters, Liquid Crystal

Power

- 9 Volt Battery

Low Battery Indicator

- "Low Battery" Appears in display when battery voltage reaches 5.8 Volts +/- 0.2 Volt.

Size

- 80 X 147 X 40 mm
- 3.15 X 5.8 X 1.6 inches

Battery Life

- 48 Hours minimum
 - With Duracell MN1604 Alkaline or equivalent

AC Input Jacks

- 130 Volts AC maximum
- 90 Volts AC minimum
- Input circuit not affected by reversed polarity

Accessories


- AC test leads with tip plugs

APPENDIX

X-RAY WAVEFORMS


This section has been added to the manual to assist users of the ECC Model 8700 Pulse Counter / Exposure Time Meter. Understanding the material in this section will enable the user to obtain the correct exposure time for any x-ray.

HALF-WAVE – This is typical of practically all dental x-rays and most podiatry x-rays.



Switch the Model 8700 to PULSE. The instrument will count and display the number of pulses. To convert to time (in seconds), refer to the Exposure Time Conversion Chart or use the formula $\text{Time} = \text{pulses} / 60$ (in countries with 60 Hz power). As shown, the 8700 would count 6 pulses, and the exposure time would be $6/60 = 0.1$ second.


FULL-WAVE – This is typical of some older hospital x-rays.



Switch the Model 8700 to PULSE. The instrument will count and display the number of pulses. To convert to time (in seconds), refer to the Exposure Time Conversion Chart or use the formula $\text{Time} = \text{pulses} / 120$ (in countries with 60 Hz power). As shown, the 8700 would count 12 pulses, and the exposure time would be $12/120 = 0.1$ second.

DC X-RAYS

This type of x-ray is typical of the larger x-rays and is multi-phase or 3 phase. A drawing of a typical waveform is shown below. A very similar waveform is also produced by capacitor discharge x-rays. These are portable, battery operated x-rays.



Switch the Model 8700 to MILLISEC. Take the x-ray exposure. The instrument will count and display the exposure time in milliseconds. For example if the x-ray is set for 2/10 second, the actual exposure time should be around 200 milliseconds.

It is important to note that the 8700 will end the count at the end of the x-ray when the intensity drops below about 70% of the peak value. This is done to ensure an accurate count when there is a "tail" at the end of the x-ray i.e. the x-ray intensity drops slowly.

If the Model 8700 is in PULSE mode, and a measurement of a DC or multiphase x-ray is taken the instrument will count and display 1. This is because the 8700 detects what is basically one pulse. Switch the instrument to MILLISEC and take another exposure.



Electronic Control Concepts

PO Box 182, 1160 US Route 50
Milford, Ohio 45150-9705 USA
Phone: 800-VIP-XRAY

Fax: 845-247-9028

sales@eccxray.com | www.eccxray.com
A Division of US Nuclear Corp
www.usnuclearcorp.com
